MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT: **REAR WINDOW DEFOGGER GRID REPAIR**

NO.	TSB-95-54-001
DATE	October, 1995
MODEL	All Models

PURPOSE

The rear window defogger grid lines can be damaged by improper window cleaning procedures or by objects placed in the rear window area causing a small scratch on the grid line(s). An open circuit results when the grid line is scratched or otherwise damaged.

Many rear window defogger grid lines can be repaired easily, quickly and economically by using a Quick Grid™ REAR WINDOW DEFOGGER REPAIR KIT marketed by Loctite Corporation. The kit, Loctite part number 15067, is available from auto jobbers and retail auto parts stores. If unavailable from your usual source, call Loctite at 800-321-9188 and ask for Customer Service. This repair kit may only be used on damaged defogger grid line areas four inches long maximum. It is the only product tested by Mitsubishi Motor Sales of America, Inc. There may be other similar products that are equally suitable for defogger grid repair.

PROCEDURE

To use the Loctite kit, follow the manufacturer's instructions on the back of the kit.

To improve the appearance of the repaired grid section, wait 30 minutes after applying the repair material, then carefully trim the excess material from the width of the repaired section with a sharp blade.



Continued

Index # 046190

FILE UNDER: Group 54 Chassis Electrical in the Dealer Service Information Binder (1426)

CIRCULATE TO: ☑ GENERAL MANAGER ☑ PARTS MANAGER ☑ TECHNICIAN

WARRANTY INFORMATION

Defogger Grid Repair
Nature Code: 99D *Cause Code:* 990
Labor Operation Number: 42322125 *Time Allowance:* 0.6 hrs.
Warranty Coverage: 36 months/36,000 miles
Special Warranty Information: Defogger grid repair on an as needed basis.

Produced by the MMSA Technical Information Department.

Copyright 1995
Mitsubishi Motor Sales of America, Inc.
All rights reserved